

1/2 Pages

## 7006-11-8 B15 Go Gauges for Caps on Finished Lamps



According to standard IEC 60061-3

## **Purpose:**

To check dimensions A max., N min. D1 min., D1 max., and the diametrical position of the pins of caps B15 on finished lamps.

## **Testing:**

The cap shall enter the gauge until the pins have passed through the slot Q. The cap is then turned through a small angle and is pressed so that the pins are in close contact with surface S. In this position, the contact making surface shall not be below surface X nor shall it project beyond surface Z.



2/2 Pages

## www.china-gauges.com



